

from the ATARI FIELD SERVICE DEPARTMENT



TRAK 20

Trak 20 can be tested the way it is described in the operations manual - TM-039

TWIN RACER

Twin racer can be tested if two (2) of the large diodes, near the LM 309, have one side lifted off the PCB on the digital board as illustrated.

The two (2) diodes that remain should be in the same configuration as the Trak 20 digital P.C.B.

